

The Högakusten Suspension Bridge - Corrosion Protection of Main Cables and Major Components



**Swedish Road
Administration:**

**Staffan Gilliusson
Ove Andersson**

COWI:

Matthew L. Bloomstine

Introduction

- Serious problems with main cable corrosion protection shortly after opening
- Main subject - retrofit of corrosion protect and operation experience
- Other major maintenance works carried out at same time: suspenders and cable bands
- Maintenance of end bearings
- Opinion on maintenance planning and the need for expertise



Description

- Opened 1998
- Far north
- Main span 1,210 m
- Total 1,800 m
- Steel box girder - dehumidified
- Carriageway 17.8 m
- 2 x 2 traffic lanes
- Concrete pylons - 180 m



Cable system

Main cables

- Parallel wire
- Ø640 and 650 mm
- Each app. 1,900 m
- Galvanized wires, zinc paste, wrapping wire and paint

Suspenders

- Locked coil, nom. Ø55 mm, 63 and 92 mm near pylons
- 2 cables per suspender, sockets both ends
- Center distance 20 m



Main cable condition

- Zinc paste omitted under construction
- Original protection defective
- Large amounts of water flowing in cables
- Forecast 2003 - depleted zinc within 10 years

Inspection 2004

- Depleted zinc on bottom wires
- Spots of ferrous corrosion
- Just 6 years after completion



Retrofit of main cable corrosion protection


- Swedish Road Administration began investigations in 2003
- Dehumidification selected as best method
- Design work tendered 2004 and COWI awarded project
- Works tendered May 2004
- Works carried out 2005, just one season - 6 months



Dehumidification system

Three main components

- Sealing system - main cables, bands, saddles, etc.
- Dehumidification system - produces and blows dry air through main cables
- Control and monitoring system - controls and verifies effectiveness



Sealing system

- Cableguard™ Wrap system
- Thickness 1.1 mm, width 200 mm
- Applied with 50% overlap for total thickness 2.2 mm
- Applied under tension with wrapping machine
- Two layers bonded with heat blanket
- Special details at bands to ensure tightness



Sealing system

Advantages

- Lowest Life Cycle Cost
- Withstands overpressure
- Environmentally friendly - no paint
- Good working environment
- Available in many colors
- Execution less sensitive to weather
- Short construction period
- Virtually maintenance free
- Long lifetime, UV and weather resistant
- Easy to remove - does not bond to cable



Dehumidification system - Main components

Dehumidification plants

- One in bridge girder at mid-span
- One in each pylon top
- Placed in buffer tanks:
 - Electrical consumption is minimized
 - Protected atmosphere for equipment
 - Good access for inspection and maintenance



Dehumidification system - Main components

Injection points

- At mid-span
- At pylon saddles



Dehumidification system - Main components

Exhaust points

- Intermediate points in main span
- In anchor houses



Control and monitoring system

The system allows:

- Remote control
- Monitoring of functionality and performance

Following is monitored:


- In buffer tanks: relative humidity, temperature, absolute water content and functionality of the plant
- At injection points: air flow
- At exhaust points: relative humidity, temperature, absolute water content and air flow
- Ambient: relative humidity and temperature

Drying out process

- System started October 2005 with set value 40% RH
- Adjusted to 20% November to speed up process
- 2 year drying out period
- Confirmed by water content exhaust = water content injection
- Calculated water removed for 300 m cable: 500 liters, corresponds to 3% of cable void volume
- Set value adjusted to 40% RH November 2007


Drying out process

First winter: Nov. 2005 - Jan. 2006




Drying out process

Second winter: Nov. 2006 - Jan. 2007




Drying out process

Third winter: Nov. 2007 - Jan. 2008



Drying out process Overview Nov. 2005 - April 2008



Dehumidification

Further operation experience

Durability of sealing system


- Ratio between exhaust flow and injection flow constant
- Indicates to leakage development

Low energy consumption

- Buffer tank solution is economical
- Running time varies over the year due to variation in ambient relative humidity
- Average running time first 2 years: 38%
- Consumption app. 40,000 kWh/year, savings of 60,000 kWh/year
- After adjustment of RH to 40% - expected consumption 25,000 kWh/year

Other works Access equipment

4 Elevator platforms, length 23 m



Other works

Access equipment

4 Cable carriages



Other works

Access equipment

2 Front loaders



Other works

Suspender cables

- Total of 18 km cable
- Feared that filler was leaking through the paint
- Original paint not as recorded
- Actually Metalcoat from Bridon
- Insufficient thickness and contamination in grooves
- Cleaned with solvent and paint with sufficient thickness



Other works

Upper sockets


- Sealing of upper sockets defective
- Material was brittle, lacked adhesion and cracked along edge
- Concave surface - water accumulation
- New solution with flexible material and plane surface



Other works

Cable band bolts

- Spot check of tension included
- Option for re-tensioning
- Reduction of forces generally app. 30% from 770 kN to 550 kN
- To fulfill design requirements bolts in 100 out of 164 cables band were re-tensioned



Maintenance

End bearings

- The PTFE sliding surface of the end bearings was subject to excessive wear
- Investigations were carried to determine if vertical loads were larger than expected
- Vertical loads were within the expected range
- Causes determined to be low operation temperature (-20°C) and excessive friction
- Solution in 2007 - new sliding surface of MSM from Maurer
- Advantages of MSM
 - Less wear at low temperature
 - Larger load capacity
 - Less friction
 - Expected movement capacity of 50 km contra 10 km for PTFE



Conclusion

- Högakusten Bridge has a main span of 1,210 m - currently the 9th longest in the world
- It is one of only two major suspension bridges in Sweden
- It is essential for SRA to acquire assistance from specialist consultants and contractors, as in-house expertise is lacking
- A comprehensive report, including future maintenance, on the works was prepared. We recommend that such a report is prepared in connection with all major works
- If such a report had been prepared in connection with the original construction some problems may have been avoided
- Much more minor and major repairs have been carried out during the first 7 years than expected



The problems are now solved - the bridge is in excellent shape and a low level of maintenance is expected for many years